EDITORIAL INDEX - 1985

BUILDING REMODELING/RETROFIT

Replacement Windows — Jan. 22
Replacement Window Roundup — Jan. 28
Window Film — Jan. 52
Replacement Windows (case study) — Jan. 92
Classical Building Renovation — Feb. 22
Specifying Commercial Carpet — Feb. 90
Modular Carpet System (case study) — Feb. 104
Ceramic Floor Tiles (case study) — Feb. 124
Lighting Retrofit (case study) — Feb. 126
Terra Cotta Restoration (case study) — Feb. 112
Energy-Saving HVAC Modifications — March 34
Boiler Retrofit/Energy Management Program (case study) — March 90
Exterior Insulation Retrofit (case study) — March 94
HVAC Retrofit (case study) — March 98
Flexible Office Design — May 20
Commercial Carpet Roundup — May 28
Carpet Tiles — May 72
Acoustical Control in the Open Office — May 80
Computer Room Design — May 88
Undercarpet Wiring System (case study) — May 94
Retrofitting Security Systems — June 22
Security Design Planning — June 50
Retrofit Air Handling System (case study) — June 84
Replacement Windows (case study) — June 100
Microwave Radio System Replaces Buried Cable (case study) — June 102
Individually-Metered Boiler (case study) — June 108
HVAC Vibration Damping (case study) — June 110
The Consulting Engineer — July 48
Static-Control Carpeting (case study) — July 92
Automatic Door Retrofit (case study) — July 96
Interior Renovation — August 20
Paint/Lighting Synergy — August 40
Retrofit HPS Lighting (case study) — August 70
Energy-Conserving Thermostatic Radiator Valves (case study) — August 76
Remodeling Case Study: The Curtis Center — Sept. 28
Remodeling Case Study: Clocktower Close — Sept. 32
Remodeling Case Study: Rye High and Middle School — Sept. 38
Remodeling Case Study: Britannica Center — Sept. 46
Remodeling Case Study: Interfirst Tower — Sept. 50
Remodeling Case Study: 901 Market Street — Sept. 58
Remodeling Case Study: 195 Broadway — Sept. 65
Remodeling Case Study: Texas Commerce Bank — Sept. 70
Remodeling Case Study: The Guthrie Building — Sept. 80
Remodeling Case Study: One Bell Central — Sept. 84
Remodeling Case Study: Sears Tower — Sept. 92
1985 Remodeling/Replacement Survey — Sept. 98
Construction Pre-Planning Program — Sept. 104
Communication and the Remodeling Team — Sept. 118
Construction Management — Sept. 138
Building Accessibility: The Value of Universal Design — Sept. 144
Exterior Wall Insulation (case study) — Sept. 158
Energy Conservation as a Remodeling Priority — Oct. 40
Multi-Faceted Energy Services (case study) — Oct. 116
Commercial Carpeting Performance Specifications — Nov. 30
Resilient Flooring and the Segmented End-User Market — Nov. 5
Asbestos and Remodeling Safety Guidelines — Nov. 58
Vinyl Wallcovering — Design Trends — Nov. 68
Elevator Modernization (case study) — Nov. 102
Plenum Cabling System (case study) — Nov. 106
Heat Pump Retrofit — Dec. 22
Avoiding Maintenance Design Errors (case study) — Dec. 30
Energy-Saving HVAC Retrofit — Dec. 50
Industrial Heat Pumps (case study) — Dec. 68
Sound Absorbent Panel (case study) — Dec. 78
Direct Digital VAV Control System Retrofit (case study) — Dec. 80

ENERGY MANAGEMENT

Replacement Windows — Jan. 22
Window Film — Jan. 52
Thermally-Efficient Urethane Foam for Roofs — Jan. 78
Stand-By Generator (case study) — Feb. 120
Aluminum Window Shades (case study) — Feb. 128
Energy/Emergency Management System — March 20
EMS Payback Strategies — March 28
Energy-Saving HVAC Modifications — March 34
Defining Energy Management — March 42
Thermal Storage Systems — March 50
Telecontrolling Energy — March 56
Stand-Alone EMS — March 66
Energy Audit Methodology — March 72
Cogeneration — March 80
Air Mixing Units (case study) — March 88
Boiler Retrofit/Energy Management Program (case study) — March 90
BAS with Fire Alarm Interface (case study) — March 92
Electrical Distribution System (case study) — March 110
HVAC Retrofit (case study) — March 98
EMS (case study) — March 120
BAS (case study) — March 106
Vibration Analysis: a Preventative Maintenance Program (case study) — March 108
Facilities Maintenance/Inventory Management — April 24
Stand-By Power System Maintenance — April 108
Controlling Energy Costs with Meters — April 116
Kilowatt Usage Meters (case study) — April 142
Daylight Sensor Lighting Control — April 154
EMS, Fire, Safety, Security Installation — June 34
Retrofit Air Handling System (case study) — June 84
Individually-Metered Boiler (case study) — June 108
Contract HVAC Maintenance — July 22
Contract Lighting Maintenance — July 30
Energy-Saving Retrofit Fluorescents — August 46
Energy-Saving Lighting Controls — August 52
Energy-Saving Interior Lighting (case study) — August 70
Energy-Conserving Thermostatic Radiator Valves (case study) — August 76
Ultrasonic Occupancy Sensors (case study) — August 77
Load Control System (case study) — Sept. 152
Cogeneration — Oct. 22
Selecting an EMS — Oct. 30
Energy Conservation as a Remodeling Priority — Oct. 40
Understanding Time-of-Day Rates — Oct. 50
Cutting Electrical Utility Costs — Oct. 62
Submetering Electrical Costs — Oct. 66
Thermal Storage Systems — Oct. 76
Cost-Effective Evaporative Cooling — Oct. 88
Energy-Saving Interior Lighting (case study) — Oct. 102
Interior Insulation (case study) — Oct. 104
EMS (case study) — Oct. 106
Window Coating (case study) — Oct. 110
BAS (case study) — Oct. 112
Outdoor Utility Submetering (case study) — Oct. 114
Multi-Faceted Energy Services (case study) — Oct. 116
EMS (case study) — Nov. 104
EMS (case study) — Nov. 110

EDITORIAL INDEX - 1985

BUILDING REMODELING/RETROFIT

Replacement Windows — Jan. 22
Replacement Window Roundup — Jan. 28
Window Film — Jan. 52
Replacement Windows (case study) — Jan. 92
Classical Building Renovation — Feb. 22
Specifying Commercial Carpet — Feb. 90
Modular Carpet System (case study) — Feb. 104
Ceramic Floor Tiles (case study) — Feb. 124
Lighting Retrofit (case study) — Feb. 126
Terra Cotta Restoration (case study) — Feb. 112
Energy-Saving HVAC Modifications — March 34
Boiler Retrofit/Energy Management Program (case study) — March 90
Exterior Insulation Retrofit (case study) — March 94
HVAC Retrofit (case study) — March 98
Flexible Office Design — May 20
Commercial Carpet Roundup — May 28
Carpet Tiles — May 72
Acoustical Control in the Open Office — May 80
Computer Room Design — May 88
Undercarpet Wiring System (case study) — May 94
Retrofitting Security Systems — June 22
Security Design Planning — June 50
Retrofit Air Handling System (case study) — June 84
Replacement Windows (case study) — June 100
Microwave Radio System Replaces Buried Cable (case study) — June 102
Individually-Metered Boiler (case study) — June 108
HVAC Vibration Damping (case study) — June 110
The Consulting Engineer — July 48
Static-Control Carpeting (case study) — July 92
Automatic Door Retrofit (case study) — July 96
Interior Renovation — August 20
Paint/Lighting Synergy — August 40
Retrofit HPS Lighting (case study) — August 70
Energy-Conserving Thermostatic Radiator Valves (case study) — August 76
Remodeling Case Study: The Curtis Center — Sept. 28
Remodeling Case Study: Clocktower Close — Sept. 32
Remodeling Case Study: Rye High and Middle School — Sept. 38
Remodeling Case Study: Britannica Center — Sept. 46
Remodeling Case Study: Interfirst Tower — Sept. 50
Remodeling Case Study: 901 Market Street — Sept. 58
Remodeling Case Study: 195 Broadway — Sept. 65
Remodeling Case Study: Texas Commerce Bank — Sept. 70
Remodeling Case Study: The Guthrie Building — Sept. 80
Remodeling Case Study: One Bell Central — Sept. 84
Remodeling Case Study: Sears Tower — Sept. 92
1985 Remodeling/Replacement Survey — Sept. 98
Construction Pre-Planning Program — Sept. 104
Communication and the Remodeling Team — Sept. 118
Construction Management — Sept. 138
Building Accessibility: The Value of Universal Design — Sept. 144
Exterior Wall Insulation (case study) — Sept. 158
Energy Conservation as a Remodeling Priority — Oct. 40
Multi-Faceted Energy Services (case study) — Oct. 116
Commercial Carpeting Performance Specifications — Nov. 30
Resilient Flooring and the Segmented End-User Market — Nov. 5
Asbestos and Remodeling Safety Guidelines — Nov. 58
Vinyl Wallcovering — Design Trends — Nov. 68
Elevator Modernization (case study) — Nov. 102
Plenum Cabling System (case study) — Nov. 106
Heat Pump Retrofit — Dec. 22
Avoiding Maintenance Design Errors (case study) — Dec. 30
Energy-Saving HVAC Retrofit — Dec. 50
Industrial Heat Pumps (case study) — Dec. 68
Sound Absorbent Panel (case study) — Dec. 78
Direct Digital VAV Control System Retrofit (case study) — Dec. 80

ENERGY MANAGEMENT

Replacement Windows — Jan. 22
Window Film — Jan. 52
Thermally-Efficient Urethane Foam for Roofs — Jan. 78
Stand-By Generator (case study) — Feb. 120
Aluminum Window Shades (case study) — Feb. 128
Energy/Emergency Management System — March 20
EMS Payback Strategies — March 28
Energy-Saving HVAC Modifications — March 34
Defining Energy Management — March 42
Thermal Storage Systems — March 50
Telecontrolling Energy — March 56
Stand-Alone EMS — March 66
Energy Audit Methodology — March 72
Cogeneration — March 80
Air Mixing Units (case study) — March 88
Boiler Retrofit/Energy Management Program (case study) — March 90
BAS with Fire Alarm Interface (case study) — March 92
Electrical Distribution System (case study) — March 110
HVAC Retrofit (case study) — March 98
EMS (case study) — March 120
BAS (case study) — March 106
Vibration Analysis: a Preventative Maintenance Program (case study) — March 108
Facilities Maintenance/Inventory Management — April 24
Stand-By Power System Maintenance — April 108
Controlling Energy Costs with Meters — April 116
Kilowatt Usage Meters (case study) — April 142
Daylight Sensor Lighting Control — April 154
EMS, Fire, Safety, Security Installation — June 34
Retrofit Air Handling System (case study) — June 84
Individually-Metered Boiler (case study) — June 108
Contract HVAC Maintenance — July 22
Contract Lighting Maintenance — July 30
Energy-Saving Retrofit Fluorescents — August 46
Energy-Saving Lighting Controls — August 52
Energy-Saving Interior Lighting (case study) — August 70
Energy-Conserving Thermostatic Radiator Valves (case study) — August 76
Ultrasonic Occupancy Sensors (case study) — August 77
Load Control System (case study) — Sept. 152
Cogeneration — Oct. 22
Selecting an EMS — Oct. 30
Energy Conservation as a Remodeling Priority — Oct. 40
Understanding Time-of-Day Rates — Oct. 50
Cutting Electrical Utility Costs — Oct. 62
Submetering Electrical Costs — Oct. 66
Thermal Storage Systems — Oct. 76
Cost-Effective Evaporative Cooling — Oct. 88
Energy-Saving Interior Lighting (case study) — Oct. 102
Interior Insulation (case study) — Oct. 104
EMS (case study) — Oct. 106
Window Coating (case study) — Oct. 110
BAS (case study) — Oct. 112
Outdoor Utility Submetering (case study) — Oct. 114
Multi-Faceted Energy Services (case study) — Oct. 116
EMS (case study) — Nov. 104
EMS (case study) — Nov. 110

Heat Pump Retrofit — Dec. 22
Evaluating Electric Motors — Dec. 36
Energy Audits — Dec. 44
Energy-Saving HVAC Retrofit — Dec. 50
Satisfying Both Owner and Tenant — Dec. 56
"Systems" Maintenance — Dec. 62
Industrial Heat Pumps (case study) — Dec. 68
HVAC Maintenance Alert Program (case study) — Dec. 76

FACILITY MANAGEMENT

Architectural Signage — Feb. 74
Energy/Emergency Management System — March 20
Teletrolling Energy — March 56
Preventative Maintenance Scheduling — April 38
Operational Cost-Cutting — April 68
Waste Management Decision Making — April 98
Preventative Maintenance
Program (case study) — April 156
Shared Tenant Services — May 42
Shared Tenant Telecommunications — May 48
Automating Facilities Management — May 56
Office Design and Productivity — May 64
Acoustical Control in the Open Office — May 80
"Intelligent Building" Basics — June 88
Information Management System (case study) — June 104
Telephone Billing in the Shared
Tenant Environment (case study) — June 106
The Consulting Engineer — July 48
Computerized Preventative Maintenance — July 54
Space Inventory via Computer-Aided Drafting — July 64
Selecting a Building Service Contract — July 72
Construction Pre-Planning Program — Sept. 104
The Successful Commercial Move — Sept. 112
Pre-Planned Purchasing of CRT,
Word Processing Systems — Sept. 126
Facilities Contract Services — Oct. 58
Building Operator Efficiency Training — Oct. 80
Corporate Facility Management: The 3M Co. — Nov. 22
Maintenance Considerations as a
Design Element — Nov. 42
Asbestos and Owner Responsibility — Nov. 64
Pre-Purchase Facility Inspections — Nov. 74
Facility Planning, Design with CAD — Nov. 78
Energy Audits — Dec. 44
Energy Management — Satisfying Both
Owner and Tenant — Dec. 56

LIGHTING

Exterior Lighting — Feb. 82
Lighting Retrofit (case study) — Feb. 126
Daylight Sensor Lighting Control — April 154
Contract Lighting Maintenance — July 30
Interior Renovation Includes
Task/Ambient Lighting — August 20
Office Lighting Design — August 28
Office Area Lighting — August 36
Paint/Lighting Synergy — August 40
Low-Wattage Fluorescents — August 46
Lighting Control Technology — August 52
Lighting Controls Roundup — August 56
Lighting System Maintenance — August 64
Retrofit HPS Lighting (case study) — August 70
Energy-Saving Interior Lighting (case study) — August 72
"Industrial Motif" Lighting (case study) — August 74
Energy-Saving Interior Lighting (case study) — Oct. 102
Lighting the High-Tech Office — Nov. 92

LIFE SAFETY/SECURITY

Security System Automation — Feb. 30
Safety, Security Lighting — Feb. 82
Asbestos Abatement (case study) — Feb. 108
Hospital CCTV Surveillance System (case study) — Feb. 116
BAS with Fire Alarm Interface (case study) — March 92
Managing Asbestos Risk — April 90
Fire Barrier Floor Sealant (case study) — April 140
Retrofitting Security Systems — June 22
Open Office Fire Safety — June 30
EMS, Fire, Safety, Security Installation — June 34
Fire/Smoke Management — June 40
Security Design Planning — June 50
Fire Suppression and Detection Systems — June 56
Recruitment, Training of Security Force — June 64
Access Control Systems — June 78
Modular Alarm Installation (case study) — June 94
Flame Resistant Bedding (case study) — June 98
Contract Safety/Security Personnel — July 46
Computerized Key Control — July 80
Fire Extinguisher System (case study) — Sept. 150
Asbestos and Remodeling Safety — Nov. 58
Asbestos: Glossary of Terms — Nov. 60
Asbestos and Owner Responsibility — Nov. 64
Hotel/Motel Fire Safety Precautions — Nov. 86

EXTERIOR/INTERIOR MAINTENANCE

Graffiti Maintenance — Jan. 38
Roof Mastics — Jan. 62
Built-Up Roofing — Jan. 70
Thermally-Efficient Urethane Foam for Roofs — Jan. 78
Single-Ply Roofing — Jan. 84
Built-Up Roofing (case study) — Jan. 96
Single-Ply Roofing (case study) — Jan. 98
Single-Ply Roofing (case study) — Jan. 100
Built-Up Roofing (case study) — Jan. 102
Single-Ply Roofing (case study) — Jan. 104
Roof Shingles (case study) — Jan. 106
Landscape Design as a Marketing Tool — Feb. 42
Washroom Design — Feb. 52
Facility Winterization — Feb. 60
Elevator System Performance — Feb. 66
Inverted Roof Membrane Assembly (case study) — Feb. 102
Asbestos Abatement (case study) — Feb. 108
Pavement Repair (case study) — Feb. 110
Public Parking Equipment (case study) — Feb. 132
Elastomeric Coating (case study) — Feb. 134
Exterior Insulation Retrofit (case study) — March 94
Eight-Layered Roofing System (case study) — March 104
Vibration Analysis: A Preventative
Maintenance Program (case study) — March 108
Conducting a Housekeeping Audit — April 32
Preventative Maintenance Scheduling — April 38
Roof Maintenance, Inspection — April 46
Measuring Maintenance Work Time — April 52
Matching Floor Care Equipment
to Procedures, Chemicals — April 60
Cleaning Chemical Glossary — April 74
Air System Hygiene Maintenance — April 82
Managing Asbestos Risk — April 90
Carpet Vacuums (case study) — April 126
Polymer Floor Polish (case study) — April 128
Single-Ply Roofing (case study) — April 134
Roof Ballast System (case study) — April 136
Standing Seam Metal Roof (case study) — April 146
Elevating Construction Platforms (case study) — April 150
Preventative Maintenance Program (case study) — April 156
Contract Grounds Maintenance/Landscaping — July 38
Computerized Preventive Maintenance — July 54
Pest Control Contractors — July 110
Single-Ply Roofing (case study) — July 84
Protective Roof Coating (case study) — July 88
Ultrasonic Bird Repeller (case study) — July 101
Roofing: Design, Installation, Maintenance — Sept. 132
Acrylic Roof Mastic (case study) — Sept. 148
Single-Ply Membrane (case study) — Sept. 154
Insulating Foam for Roofs (case study) — Sept. 156
Exterior Wall Insulation (case study) — Sept. 158
Door System (case study) — Oct. 108
Maintenance Considerations as a
Design Element — Nov. 42
Resilient Flooring and the Segmented
End-User Market — Nov. 50
Single-Ply Roof Membrane (case study) — Nov. 108
Avoiding Maintenance Design Errors — Dec. 30
Evaluating Electric Motors — Dec. 36
"Systems" Maintenance — Dec. 62
Boiler/Machinery Risk Management — Dec. 64
Color-Coded Mechanical Plant (case study) — Dec. 70
Polymer Floor Polish (case study) — Dec. 72
Single-Ply Roof Membrane (case study) — Dec. 74